



PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2018-SAV-0162

Date: 8/16/2019

Page 3 of 5

Tag #: 3354

JobName: Francis Lake

Labor and Other Charges:

Qty	PartNo	Description	Sell Price	Total Price
11	14-69 00 03A	LABOR,SVC FLYGT,NO TAX Z4-TP MODELS: 3000,7000,8000	\$102.00	\$1,122.00
1	14-69 00 21D	ENV FEE >50HP TP ENVIRONMENTAL FEE	\$87.00	\$87.00
1	14-69 00 24B	MISC ITEMS,LARGE PUMPS TP MATERIALS,LUBES,SOLVENTS,ETC	\$80.00	\$80.00

Total Price: \$37,884.90

Product Replacement

Product Number: 3301.185-0258

Estimated Delivery: 8-10 Weeks

Cost of New Unit: \$49,103.25

Description:

Flygt Model NP-3301.185 10" volute Submersible pump equipped with a 460 Volt / 3 phase / 60 Hz 85 HP 1150 RPM motor, 638 impeller, 1 x 50 Ft. length of SUBCAB 3x50+2G35/2+S(2x0,5) submersible cable, FLS leakage detector, volute is prepared for Flush Valve

Terms

Please note: If additional repair requirements are identified during service, the total cost of your repair may change. Should this occur, we will contact you for approval before proceeding.

A signed Purchase Order or approval below must be received before any repair work can begin.

If repaired unit is not picked up or delivered within 5 days of completion, the repair will be invoiced.

Taxes: State, local and other applicable taxes are not included in this quotation.

Terms of payment: Net 30 Standard



Flygt Products
128 A Airport Park Drive , Garden City GA 31408
PH: (912) 966-1577
FX: (912) 966-1579

