

	<p>schedule specified for each BMP in the SWMP. The measurable goal must be specified for each BMP. Each BMP must be executed at least annually.</p> <p>1.c. Details on the implementation of each BMP, including the status of implementation, must be provided in each annual report.</p>
--	---

4.2.3 Illicit Discharge Detection and Elimination (IDDE)

The permittee must develop, implement and enforce a program to detect and eliminate illicit discharges (as defined in 40 CFR Part 122.26(b)(2)) into its MS4. The permittee must:

- 4.2.3.1 Develop, if not already completed, a storm sewer system map, showing the location of all outfalls and the names and location of all waters of the State that receive discharges from those outfalls;
- 4.2.3.2. Prohibit through ordinance, or other regulatory mechanisms, non-stormwater discharges into the MS4 and implement appropriate enforcement procedures and actions;
- 4.2.3.3 Develop and implement a plan to detect and address non-stormwater discharges including illegal dumping to the MS4;
- 4.2.3.4 Inform public employees, businesses, and the general public of the hazards associated with illegal discharges and improper disposal of wastes; and
- 4.2.3.5 Address the following categories of non-stormwater discharges or flows only if they are identified as significant contributors of pollutants to the MS4:
 - water line flushing;
 - landscape irrigation;
 - diverted stream flows;
 - rising ground waters;
 - uncontaminated ground water infiltration (as defined in 40 CFR Part 35.2005(20));
 - uncontaminated pumped ground water;
 - discharges from potable water sources;
 - foundation drains;
 - air conditioning condensation;
 - irrigation water;
 - springs;