

## SECTION 5 – LIST OF DOCUMENTS

August 25, 2021

1. Drawings and Specifications prepared by Gladwin Vaughn Architecture as referenced below.

Page #	Description	Date
	<b>Architectural</b>	
A1.02	Basement Floor Plan - Demolition	7/30/2021
A1.12	First Floor Plan - Demolition	7/30/2021
A1.22	Second Floor Plan - Demolition	7/30/2021
A1.32	Third Floor Plan Demolition	7/30/2021
A1.41	Attic Plan - Demolition	7/30/2021
A2.02	Basement Reflective Ceiling Plan - Demolition	7/30/2021
A2.12	First Floor Reflective Ceiling Plan - Demolition	7/30/2021
A2.22	Second Floor Reflective Ceiling Plan - Demolition	7/30/2021
A2.32	Third Floor Reflective Ceiling Plan - Demolition	7/30/2021
	<b>Electrical</b>	
E1.01	Electrical Demolition Plan	7/30/2021
E1.02	Electrical Demolition Plan - Basement, 1st, 2nd & 3rd Floor	7/30/2021
Spec #	Description	Date
	<b>Architectural</b>	
3119	Existing Conditions Information	7/9/2021
3126	Existing Hazardous Material Information	7/9/2021
11000	Summary	7/9/2021
13233	Photographic Documentation	7/9/2021
13591	Historic Treatment Procedures	7/9/2021
15000	Temporary Facilities and Controls	7/9/2021
17300	Execution	7/9/2021
17419	Construction Waste Management and Disposal	7/9/2021
24119	Selective Demolition	7/9/2021
24296	Historic Removal and Dismantling	7/9/2021
28716.13	Bird Excrement Removal	7/9/2021
Appendix A	Asbestos Containing Material Survey	7/9/2021
Appendix B	Lead Based Paint Survey	7/9/2021